



Field Sampling Technician's Report

Client Company

Key Rentals Ltd

Nuron Commercial Division Ltd

Job number

2577

Sampling Location

22A Ruawai Rd, Mt Wellington, Auckland

Conducted on

2/7/17, 8:25 AM

Prepared by

Auckland Meth Testing

Completed on

2/7/17, 8:36 AM

Terms of Use, Content and Scope of Work

The content included in this report, including all the text, graphics, photographs, logos, and images (Content), is the property of Meth Testing New Zealand Limited (MTNZ) and is protected by New Zealand and international copyright and trademark laws.

This report has been prepared for the sole use of the contracting party. The Content is private and confidential and may not be circulated without the contracting parties consent or the prior written consent of MTNZ.

Any other use of the Content, including but not limited to, the reproduction, modification, distribution, transmission or republication in full or in part is strictly prohibited.

MTNZ reserves the right to notify affected parties if contamination and associated health risks are discovered.

Disclaimer of Warranty

The property in question has been tested for methamphetamine contamination by MTNZ in accordance with Ministry of Health guidelines for the remediation of clandestine methamphetamine laboratory sites. Testing was undertaken without bias, in an impartial and objective manner.

The test was undertaken in compliance with occupational health and safety guidelines. In order to protect our staff and minimise cross contamination, appropriate personal protective equipment was used.

MTNZ chose the location of sample sites based on industry knowledge of the most likely contamination points.

Although we strive to maintain the accuracy of each report and update our procedures regularly, you should be aware of the following constraints affecting the Content:

1. The very nature of methamphetamine laboratory sites and the use of methamphetamine by third parties is secretive and clandestine. While every effort is made to detect contamination, methamphetamine production and use may have been deliberately concealed by third parties. To combat this, we endeavour to update our data and procedures regularly. MTNZ makes no warranty as to the completeness, accuracy, currency, or reliability of Content.
2. Our tests are not comprehensive, nor does this report contain all information that may be relevant. Content provided in this report is only general information and is only intended to provide an indication of methamphetamine presence. We provide no warranty or guarantee for any information provided by this report.

Limitation of Liability

We shall not be liable – whether in contract, tort or otherwise – for any consequential, indirect or special damage or loss of any kind whatsoever suffered by you in connection with you using or relying upon this report or its content.

Scope of work.

The property in question has been tested for methamphetamine contamination by Meth Testing New Zealand. These tests have been undertaken without bias and in an objective manner. The sampler who entered the property took the precaution of wearing PPE to protect themselves and ensure risk of cross contamination was minimised. Meth Testing New Zealand chose the location of sample sites based on industry knowledge of the most likely contamination points.


Table of Contents

FIELD SAMPLING TECHNICIAN'S REPORT	1
Terms of Use, Content and Scope of Work	2
HEALTH AND SAFETY	4
PROPERTY DESCRIPTION	5

Health and Safety

Field Sampling Report	Sampling	Report
Are there any hazards or risk identified?	NO	

Property Description

Field Sampling Report	Sampling	Report
External Property Photo		
 <p>Appendix 1</p>		
Type of dwelling	Unit	
Number of bedrooms	1	
Walls are:	Paint, Wood	
Flooring is:	Vinyl, Concrete	
Window dressings are:	Other	
Type of garaging	Single - External	
All areas in property	Bedroom 1 - BD1, Bathroom - BTM, Kitchen - KTN, Office - OFF, Toilet - TOI	
Areas not sampled	Dining Room - DNR, Laundry - LDY	
Does the property contain carpeted areas?	Contains No Carpeted Areas	
Property is:	Vacant	
Any Additional Comments	Laundry and Dining room not sampled as requested, because they are open spaces.	

Visual Site Inspection Details

Field Sampling Report	Sampling	Report
Outside dwelling:	Grass, Concrete	
Any signs of methamphetamine manufacture	NO	
Any signs of recreational methamphetamine usage?	NO	
Barcode Scanner	2TKAE20 7334625210	



Appendix 5



Appendix 6



Appendix 7



Appendix 8



Appendix 9



Appendix 10



Appendix 11